
RE 129 CONTROL CARD FOR SMALL PLASMA CUTTING MACHINE



Function:

-At start open air valve ,after 1" start HF and pilot arc (for 2") , and turn on power supply.

-At stop turn off power supply and after 60" close valve.

