
Control board for a 3 phase full controlled bridge in a mig welding machine





- Voltage regulation working in open loop.
- Command for an auxiliary source for base current.
- Auto balance of wave.

